PORTLAND HARBOUR AUTHORITY LTD.

Local Notice to Mariners
No 05/2025 (T)

NAVIGATIONAL LIGHTS INTERMITTENT

The navigational lights at the following locations are solar powered and are currently affected by low sunlight levels, leading to intermittent operation during the latter half of nighttime hours. Defect rectification in process.

Q Pier Knuckle – Fl.R.2s - 50° 34.346 'N - 002° 26.420 'W

Safewater Mark – Morse A 10s (White) - 50° 35.200 'N - 002° 27.250 'W

New Channel Beacon – L.Fl 10s 3m 5M (White) - 50° 34.899 'N - 002°27.694 'W

South Ship Channel – Morse U 15s 12m 5M (White) - 50° 34.150 'N - 002° 25.340 'W

Mariners are advised to keep a sharp lookout when in the vicinity of the lights listed above during hours of darkness.

This notice is issued under the powers vested by the Portland Harbour Revision Order 1997.

Captain M Shipley
General Manager (Marine)
21st January 2025

Owners, Agents, Yacht Clubs and Recreational Sailing Organisations should ensure that the contents of this notice are made known to the Masters or persons in charge of their vessels or craft.